

## Community Living Arrangement Inspection Report Summary

**Oak Ridge Road**

370 Oak Ridge Road Stratford, CT 06497

**R-757**

Prime Care, Inc.

Inspection Date: Thursday, August 20, 2015

DDS Region: West

Inspection Type: Revisit

### Inspection Report Citations Were Reported In The Following Regulatory Areas:

#### Regulatory Category

#### **17a-227-11 Physical Requirements**

11d Hazard prevention

#### **17a-227-12 Emergency Planning**

12a Residence emergency plan